DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-020406 Address: 333 Burma Road **Date Inspected:** 09-Aug-2010

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 700 **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Yan Hua No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component: OBG** Segment Assembly

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Ramesh Gade, was present during the times noted above for observations relative to the work being performed.

This QA Inspector performed the following work:

Bay 14 – OBG Segment 12AW

Shielded Metal Arc Welding (SMAW) in the 4G position of PP112 Floor beam bottom flange weld # FB3081-001-164. The welder is identified as 067589. ZPMC Quality Control (QC) is identified as Li Ping. The welding variables recorded by QC appeared to comply with WPS-B-P-2214-B-U2-FCM-1. See attached photograph Pic_001.

Bay 14 – OBG 13CW Su Assy

Sub Arc Welding (SAW) in the 1G position of 13CW sub assy plate BP3065A to BP3066A splice weld # SEG3015A-006. The welder is identified as 045270. ZPMC Quality Control (QC) is identified as Guoxing Hui. The welding variables recorded by QC appeared to comply with WPS-B-T-2221-B-L2c-S-2. See attached photograph Pic 002.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Bay 14 – OBG Segment 12CW

During in process visual inspection this QA Inspector observed ZPMC NDT personnel performing Ultrasonic Testing (UT) on Cross Beam side Lifting Bracket.

Bay 14 – OBG Segment 12CW

Flux Core Arc Welding (FCAW) in the 2G position of Counterweight side Lifting Bracket weld # SEG3006M-226. The welders are identified as 201215. ZPMC Quality Control (QC) is identified as LI ping. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-TC-u4b-F.


Bay 15 – Cross Beam CB17

Shielded Metal Arc Welding (SMAW) in the 2G position of floor beam flange weld #FB3057-056-069. The welder is identified as 054460. ZPMC Quality Control (QC) is identified as Feng Ya Jun. The welding variables recorded by QC appeared to comply with WPS-B-P-2212-B-U2-FCM-1.

West Tower Lift 2 – Blast shop 1

This QA inspector performed Visual Inspection of West Tower Lift 2 external skin A, B, C, D, and E after Blasting.





Summary of Conversations:

No relevant conversations reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (+86)15000 42 2372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Gade,Ramesh **Inspected By:** Quality Assurance Inspector

Reviewed By: McClendon, Timothy QA Reviewer